Richmond Refinery LPS Bulletin – Environmental

Sulfur Spill at SRU #1





IMPACT ERM Loss#: 31765 Investigation# 19063

Location: Richmond Refinery, Cracking Division, SRU #1 Train

Contact Information:

Megan Bleckinger 510-242-2288

mgzi@chevron.com



Sulfur leak to grade



Sulfur overflowing from Look Box

Tenets of Operations Violated:

Tenet #1 – Operate within design and environmental limits

Incident Description:

On the afternoon of February 19, 2012, an operator discovered a sulfur spill to secondary containment out of the 3rd seal of the SRU #1 Train condenser. The operator immediately notified the Head Operator and Shift Team Leader. The operating crew then proceeded to unplug the 2" drain line to the sulfur pit and Maintenance completed the clean up the following day.

The spill was estimated at six barrels.

Investigation Findings:

- 1) The basket inside the look box was fine earlier in shift.
- 2) The 2" drain line was blocked with sulcrete (a sulfur coke like material).
- 3) There was no routine duty to inspect the drain line under the basket to determine that it was clear.

What Worked Well:

1) Operations responded quickly to address the abnormal conditions by unplugging the drain line, thus minimizing the spill.

Recommendations:

- 1) Clear the #2 and #3 SRU train condenser drain lines to prevent a similar incident.
- 2) Add a Routine Duty to the IntelaTrac handhelds to clear the 3rd seal 2" drain line on all three trains.
- 3) Investigate the origin of the sulcrete found in SRU #1.



This document is intended for workforce personnel only. Nothing herein should be construed as a legal determination of causation or responsibility. The company makes not representations or warranties, express or implied, about the thoroughness, accuracy, or suitability of use by others of any of the information contained herein.